

## LYCOMING AIRCRAFT ENGINE REPAIR SERVICES TECHNICAL SPECIFICATIONS

1. Purchase of overhaul services for LYCOMING aircraft engines (hereinafter referred to as the Services):

<i>No.</i>	<i>Engine name</i>	<i>Engine model</i>	<i>Engine serial number</i>
1	LYCOMING	O-235-L2C	L-12746-15
2	LYCOMING	IO-360-L2A	L-34810-51E
3	LYCOMING	IO-360-L2A	L-34940-51E
4	LYCOMING	IO-360-L2A	L-34965-51E

2. Overhaul services for LYCOMING aircraft engines must be performed in accordance with the latest Lycoming (manufacturer) documentation and all applicable directives, maintenance bulletins, and other documents governing these Services.

3. During overhaul of engines, the following additional components must be replaced with new, manufacturer-repaired or FAA/EASA-approved, overhauled components using original parts:

- Magneto;
- Ignition harness;
- Spark plugs;
- Oil filter;
- Carburetor (only for O-235-L2C engines);
- Fuel injection systems parts (only for IO-360-L2A engines);
- Engine-driven fuel pump (only for IO-360-L2A engines);
- Oil quick drain valve;
- Alternator 24V;
- Starter 24V.

4. After overhaul, the engine must be tested on a test bench.

5. Certificates of release to service (EASA Form 1 or FAA Form 8130-3) must be issued for the services provided and parts replaced and submitted together with the repair file for each engine.

6. Parts that are found to be unsuitable must be replaced with new original parts from the engine or unit manufacturer (not included in the list in point 3), which shall be purchased separately, paid for and delivered by the Contracting Authority.

7. After overhaul, the engine must be given a minimum service life recommended by the manufacturer of 2,400 hours (for O-235-L2C engines) and 2,000 hours (for IO-360-L2A engines),

and a warranty period of not less than 6 (six) months from the start of engine operation or not less than 500 operating hours. (for IO-360-L2A engines) and a warranty period of not less than 6 (six) months from the start of engine operation or not less than 500 operating hours.

8. If the service provider wishes to assess the cost of the work, the contracting authority shall allow it to inspect the engine at an agreed location before submitting its tender.

9. The service provider undertakes, within 14 calendar days of the date of receipt of each engine, to:

9.1. perform a defect detection of the LYCOMING engine;

9.2. assess the need for additional parts for the LYCOMING engine;

9.3. submit a report on the LYCOMING engine defect detection and the need for additional parts to the Contracting Authority.

10. The Service Provider must perform the above-listed work (points 3 and 9 of the technical specifications) for each engine within 6 (six) weeks from the date of receipt of that engine. If the Service Provider determines that additional parts are required, the deadline for the provision of services shall be suspended from the date of submission of the defect report/statement to the Contracting Authority until the Contracting Authority delivers the parts to the Service Provider. The Contracting Authority undertakes to deliver the parts specified in the defect report/statement to the Service Provider no later than within 3 (three) months. After receiving the parts, the deadline for performing the work shall be 4 (four) weeks.

11. The contracting authority shall deliver the engine to the service provider for repair at its own expense.

12. The service provider shall insure the repaired engine at its own expense and send it back to the contracting authority at the following address: Lakūnų st. 7D, Kyviškių village., LT-13132 Vilnius district.

13. During the provision of services, the Service Provider shall be fully and materially responsible for the storage and delivery of the repaired engine to the Customer.

14. The Service Provider agrees that the Customer may audit the Service Provider's Technical Maintenance Organization.

15. The service contract shall be concluded for a period not exceeding 8 (eight) months from the date of its signing.



**Vilnius, Lithuania**  
**2025-06-08**

The translation was performed by the translation office - MB "Greitasis vertimas", legal entity code: address: 306992399, address: Krivių st. 5, LT-01204 Vilnius

confirm the translation of these documents from Lithuanian to English and confirm that the translation is authentic to the original.

