



1F1p



2F1p

6H1p



7B1p



7B1p



1002p



14M1p



18D1p



19H1p





20F1p



**Degalinės rezervuarai
r1-r14**

A photograph showing a concrete retaining wall in a grassy area. The wall is made of several sections and appears to be in poor condition, with some peeling paint and visible cracks. Behind the wall, there are various plants and trees, including a large tree with dense foliage and a birch tree with white bark. The ground in the foreground is covered with green grass. The sky is overcast.

**Kiti inžineriniai
statiniai**